Work Order (Bid Form)

AUDITOR: Anndra Jackson

(901) 864-2903 anndraj@gmail.com

WORK ORDER INFORMATION	N
------------------------	---

Work Order Name: WO/90009MD2632
Work Order Type: Weatherization
Audit Name: 90009MD2632

CLIENT INFORMATION

Client Name: Address:

Client ID: 90009MD2632

Alt. Client ID:

<u>AGENCY INFORMATION</u>

Agency: Metropolitan Development and Housing Agency

Agency Phone: (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

Nashville, TN 37206 Email Address:

Agency Contact: JACKSON, ANNDRA R Work Phone:

Cell Phone: (901) 864-2903

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Site Built 1950 SQ FT 768 Wood Exterior/Drywall Interior Auditor ANNDRA JACKSON Conducted 3/26/2012

	Measure 1 Infilt	ration Redctn			Componen	ts			Inspected
C	2) wd2-3 3) wd10-4) wd3-3 5) Wd4- 6) wd5-3 7) wd6-2 8) wd7,8 9) WD9- 10) DR1 11) DR2 12) seal 13) Insta	49X56-Reglaze, c/s ext. 32x56-reglaze, c/s ext. 32X80-BACK DR-c/s ext. 32X80-BACK	nd int. epair ext s and int at t all d/s and kt. Install d t door	op and w/s. /s and	on approx 39 d bottom. replace w/s				
	,	ace hatch cover for attic			stall eyes h	ooks to s	ecure.	A -41	
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
10	Miscellaneous Su	Infiltration Reduction	Each	1					70.0.
	Other Detail Field Notes:			Measur	e Sub Total:			Sub Total:	
	riela Notes:								

Report Run On: 4/8/2012

Λ	leasure 2 DWH	l Tank Insulation			Componen	ts			Inspected
Co	omment 40 Elect	DWH							
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
0	ther Detail								
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								
		I Pipe Insulation			Componen	ts			Inspected
		I Pipe Insulation st 5ft of water lines			Componen Estimated			Actual	Inspected
Co		-	Units	Qty	-		Qty		Inspected Total
C (omment Wrap firs	st 5ft of water lines	<i>Units</i> Each		Estimated		Qty	Actual	
C (omment Wrap firs	st 5ft of water lines Description / Comment		Qty	Estimated		Qty	Actual	
C (4) # 1 2	omment Wrap firs Material / Labor Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1 2	omment Wrap firs Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
C (4) # 1 2	omment Wrap firs Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
C (4) # 1 2	omment Wrap firs Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated			Actual	
# 1 2 O	omment Wrap firs Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# 1 2 <u>0</u>	omment Wrap first Material / Labor Insulation Labor ther Detail	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Somment 2x8x16 SQ FT 7 No floor Material / Labor Insulation	768 insulation existing. Obse	erved mois						
			sture in	left corner of	of baseme	ent.		
				Estimated			Actual	
Insulation	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Tota
	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	768					
Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	768					
ther Detail								
			Magazir	e Sub Total:			Sub Total:	
			Weasure	Sub Total.			Jub Total.	
comment Wood e	xt/drywall int			-	WL4N			
Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	 Total	Qty	Actual Unit Cost	
Material / Labor	Description / Comment	Ullits	Qty	Onit Cost	Total	Qty		Tota
Insulation	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	746.7				Onit Cost	Tota
	Wall Insulation - Cellulose, Blown - 2x4	SqFt SqFt	746.7 746.7					Tota
Labor	Wall Insulation - Cellulose, Blown - 2x4 Filled Wall Insulation - Cellulose, Blown - 2x4	·						Tota
Labor	Wall Insulation - Cellulose, Blown - 2x4 Filled Wall Insulation - Cellulose, Blown - 2x4	·						Tota
Insulation Labor Other Detail	Wall Insulation - Cellulose, Blown - 2x4 Filled Wall Insulation - Cellulose, Blown - 2x4	SqFt	746.7	e Sub Total:			Sub Total:	Tota

Report Run On: 4/8/2012

	Measure 6 Smo	ke Detector is Needed			Componen	ts		I	nspected
C	omment Install in	living room							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1					
2	Labor	Labor	Each	1					
(Other Detail			1			1		
				Measur	e Sub Total:] :	Sub Total:	
	Field Notes:								
L									
			Work O	rder Gra	nd Total:		Gran	d Total:	